Creasing and Folding are critical steps in the box forming process


Dipl. Ing. Lukas Pescoller





Paperboard is ...

- A thick, single or multiply paper based material.
- composed of several layers of pulp fibers with preferred orientation
- bonded by starch or adhesive material
- Bending stiffness is one of the most important mechanical properties for paperboard packaging
- bending stiffness is mainly attributed to the outer plies with higher Density



[Source: Hui Huang, KTH Stockholm]




The Creasing process


- Fiber-fiber bonds between plies are broken
- Some fibers are damaged
- Plastic deformation occurs
- Sheare, tension and compressing stresses arise




- Locally reduced bending stiffness
- Creased area = hinge



The creasing process






[Source: Hui Huang, KTH Stockholm]



The folding process:


- Folding uncreased paperboard results in cracks on the outside
- The ability to delaminate (fracture surface in parallel to the plies) is an important property for folding


- Tensile stress arises on the outside ply (Spine)
- The inner plies (Bead) are compressed and bulging
- Deformation and delamination takes place



A crease is a double fold


The folding process





[Source: Hui Huang, KTH Stockholm]

Analyze the Bead with CREASY




The Bead width – a delamination parameter


the distance between the twin folding points

Problems with wide bead:

- Un-sharp folding points
- Insufficient internal delamination and inflexibel beat
- ■Low flexibility beat gets crushed during folding
- Hard contact at the intersection between side and bead
- ■Extensive tension stress on spine
- Spine fracturing or crease end splitting



Extensive Tension






The folding point sharpness defines the symmetry of the bead

Non symmetric folding points

- Off-center folding
- non uniform boxes
- ■Extensive stress in an arrow area of the spine
- Fracturing and folding failure







Reasons for assymetric bead

- Parallel crease close to each other
 - limitation in material stretch
 - Competition in drawing the material
 - Each crease is poorly formed
 - With assymetric bead
 - Assymetric internal delamination
 - The resistance to crease formation grows fast after a critical distance

theory







practice


Reasons for assymetric bead

- Rule channel misalignment
- Tool to tool misalignment (tolerance mismatch)
- Crease rule dish
- Incorrect laser dieboard cutting vertically

Have a look at the adjustment proposal in 0.01mm resolution:








Symmetry	0.08
----------	------

The bead height as an indicator for the penetration depth

- The knife consumtions changes the penetration depth of the rule
 - changing the tension forces which could result into diecut edge chipping or flaking,
 - or in breaking the card board material
 - or faster erode the upper corners
 of the crease channel






Crease cross section analysis with CREASY


- Measure beat
- Rotate sample by 180°




Measure crease

The software will overlay the two images showing the result in terms of a card board cross section











Compare crease before and after first break


- The first break defines the final location of the twin folding points
- The first break defines the final symmetry of the folding
- The first break shows problems with cracks, fracturing and folding failures






Control the final product box quality with CREASY

- The box angle should be as sharp as possible
- The box angle should be as symetric as possible
- The angle between the folding panels should be close to 90°





Why control of creasing is important

- No customer will accept cracks and splitting on folded packaging products
- No customer will accept non-uniform packaging boxes
- The paper structures and folding behaviour vary with
 - □ Fiber lengts, fiber content, fiber orientation
 - Coatings, bond between coating and paper
 - Printed ink, varnish
 - Heat to dry the ink of the print sheet reduces flexibility
 - Environment humidity in the pressroom
- The cutting & creasing process itself has variations
- Help to avoid runnability problems on the packaging line
- Help to avoid waste because of un-usable boxes

Thank you...

See what happens Understand why it happens Take corrective actions